

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
			4 S 17W			1.2		3.8				auf				
			3 S	0.0				3.0			»	»	»	»		
			2 S 30O	1.0				1.7			»	»	»	»		
			2 S 45O	1.4				1.4			»	»	»	»		
			3 S 25W			1.3		2.7			»	»	»	»		
			3 S 45O	2.1				2.1			»	»	»	»		
			2 S 45W			1.4		1.4			»	»	»	»		
			3 S 70W			2.8		1.0			»	»	»	»		
			1 N 77W			1.0	0.2				»	»	»	»		
			3 N 65W			2.7	1.3				»	»	»	»		
			3 S 80W			3.0		0.5			»	»	»	»		
			4 S 73W			3.8		1.2			»	»	»	»		
			2 S 45W			1.4		1.4			»	»	»	»		
			5 S 80W			4.9		0.9			»	»	»	»		
			2 W			2.0		0.0			»	»	»	»		
			2 S 78W			2.0		0.4			»	»	»	»		
			3 S			0.0		3.0			»	»	»	»		Scharfkantiger Schutt
			3 S 13O	0.7				2.9			»	»	»	»		
			2 S 32O	1.1				1.7			»	»	»	»		
			1 S 30O	0.5				0.9			»	»	»	»		
			5 S 10W			0.9		4.9			»	»	»	»		
			6 S 45W			4.2		4.2			»	»	»	»		
			2 S 45W			1.4		1.4			»	»	»	»		
			6 S 40W			3.9		4.6			»	»	»	»		
			2 S 45W			1.4		1.4			»	»	»	»		
			3 S 15O	0.8				2.9			»	»	»	»		
			7 S 46W			5.0		4.9			»	»	»	»		
			2 S 80O	2.0				0.3			»	»	»	»		
			2 S 50O	0.2				2.0			»	»	»	»		
			2 W			2.0		0.0			»	»	»	»		
			5 S 60W			4.3		2.5			»	»	»	»		
			5 S 85W			5.0		0.4			»	»	»	»		